



Wimmera River Reach 2 Waterway Action Plan



January 2003

© Earth Tech Engineering Pty Ltd

All Rights Reserved. No part of this document may be reproduced, transmitted, stored in a retrieval system, or translated into any language in any form by any means without the written permission of Earth Tech Engineering Pty Ltd.

Intellectual Property Rights

All Rights Reserved. All methods, processes, commercial proposals and other contents described in this document are the confidential intellectual property of Earth Tech Engineering Pty Ltd and may not be used or disclosed to any party without the written permission of Earth Tech Engineering Pty Ltd.

Earth Tech Engineering Pty Ltd ARN 61 089 482 888

ABN 61 089 482 888 Head Office 71 Queens Road Melbourne VIC 3004 Tel +61 3 **8517 9200**



Wimmera Catchment Management Authority

Wimmera River Reach 2 Waterway Action Plan

Contents

Introduction	1
Regional Objectives	3
Review of Regional Strategies	
The Victorian River Health Strategy	
The Wimmera Waterway Management Strategy	4
The Wimmera Water Quality Strategy	
The Wimmera River Geomorphic Investigation	
River Health Assessment	
Overview of Reach 2	
Overview of Reach 2 tributaries	
Little Wimmera River Tom the Tailor Creek	
Hickman Creek	
Rocky Creek	
Sandy Creek	
Glenpatrick/Nowhere Creek	
Other tributaries	12
Overview of Management Reaches	13
Reach 2.1 - "Hanging Swamp" to Lower Wimmera Road	
Reach 2.2 - Lower Wimmera Road to end of poplars	
Reach 2.3 - End of poplars to Drop Structure upstream of Hickman's Creek	
Reach 2.4 - Drop Structure upstream of Hickman's Creek to Glenlofty Creek	16
References	19
Appendix A: Proposed Program of Activities for Reach 2	20
Reach 2.1 - "Hanging Swamp" to Lower Wimmera Road	21
Management Objectives	21
Reach 2.2 - Lower Wimmera Road to end of poplars	22
Management Objectives	
Tom The Tailor Creek	
Management Objectives	
Management Objectives	
Reach 2.3 - End of poplars to Drop Structure	
Management Objectives	
Reach 2.4 - Drop Structure upstream of Hickman's Creek to Glenlofty Creek	25
Issues Arising From the Works Program	27
Instream Reed Growth	
Loss of Stock Watering Holes	27
Increased Flooding Due to Reeds	27
Increased Fire Hazard Due to Reeds	
Increased Flooding Due to Large Woody Debris	
Appendix B: Plan of Survey and Cross Sections, Wimmera River Elmhurst	29
Appendix C: Hanging Swamp Stability Assessment	30

Appendix D: Wimmera River Reach 2, Landholder Property Boundaries...... 31

Introduction

This Waterway Action Plan for Reach 2 of the Wimmera River has been prepared by Earth Tech Engineering for the Wimmera Catchment Management Authority.

The Wimmera Catchment Management Authority plans to undertake a stream management works program along this reach of the Wimmera River, which has been identified as a high priority for management. This Waterway Action Plan has been completed to help facilitate the implementation of the waterway management works. The development of local community support, the investigation of reach wide issues and the subsequent provision of a technical and financial basis for the works to government, are important aspects of this Action Plan.

This report includes a discussion of stream processes, habitat, riparian vegetation, stream flow and water quality issues and establishes a technical basis for determining the priorities for works implementation. In determining these priorities the investigation also considers the objectives of the Wimmera Catchment Management Authority via objectives referenced in the relevant regional strategies.

Once these priorities have been set, the works program will be developed in consultation with the local community. Individual works sites will be assessed in the field against the priorities set for the program and associated financial considerations.

Regional Objectives

The regional strategies and policies which are relevant to the Wimmera River Catchment are the:

- Victorian River Health Strategy (2002)
- Draft Wimmera Waterway Management Strategy (2002)
- Draft Wimmera Water Quality Strategy (2001)
- Wimmera River Geomorphic Investigation (2002)

Review of Regional Strategies

The Victorian River Health Strategy

The objective of the Victorian River Health Strategy (VRHS) is to achieve healthy rivers, streams and floodplains which meet the environmental, economic, recreational and cultural needs of current and future generations (DNRE, 2002). This goal is to be attained using the following four key elements of the strategy (DNRE, 2002):

- Protecting rivers that are of the highest community value from any decline in condition:
- Maintaining the condition of ecologically healthy rivers;
- Achieving an 'overall improvement' in the environmental condition of the remainder of rivers, and;
- Preventing damage from future activities.

Implementation of this management approach will be by:

- Providing special protection for rivers of very high value;
- Establishing regional five and 10 year targets for river protection and restoration through community-driven regional planning processes; and
- Establishing policies for specific management activities aimed at preventing damage to river health from future management activities.

Regional River Health Strategies, of which this report is a part, aim to:

- Identify environmental, recreational, social and economic assets;
- Identify threats to assets;
- Set broad priorities for protection and restoration based on a risk-based approach and a level of community commitment;
- Identify broad actions required;
- Include detailed issue specific action plans which identify:
 - Detailed options for actions and analyse these using the cost-benefit approach;
 - Priority actions;
 - Roles and responsibilities;
 - The cost sharing arrangements;
 - Timetable for implementation; and

- Five year implementation targets and 10 year resource condition targets;
- Integrate five year implementation targets and 10 year resource condition targets for major river reaches;
- Set integrated river health objectives and targets for major river reaches; and
- Include monitoring, reporting and review programs.

The VRHS goes on to briefly describe some of the details of managing:

- Water quality;
- · Riparian lands; and
- River channels.

The Wimmera Waterway Management Strategy

The Wimmera Waterway Management Strategy (WWMS) aims to provide direction for waterway management within the Wimmera region (Sinclair Knight Merz 1999). The goal of the strategy is to, "protect and enhance the region's waterways through fair and sustainable management, taking account of environmental, economic, cultural and social objectives. In 1997 the Wimmera Regional Catchment Strategy recognised the need to develop and implement an integrated waterway management program for the two river basins within the Wimmera CMA region. A series of programs, which are consistent with the Wimmera Regional Catchment Strategy, are detailed in the WWMS. Of particular relevance to this Waterway Action Plan are:

- Program 1. Asset Management, the aim of which is to manage structural waterway assets so as to improve the health of the waterways;
- Program 2. Waterway Repair and Maintenance, the aim of which is to preserve, maintain and/or rehabilitate the environmental, economic and social values of waterways;
- Program 3. Riparian Management, the aim of which is to improve waterway health through the sustainable management of riparian zones; and
- Program 4. Catchment Management, the aim of which is to assist in addressing land management issues that have negative impacts on waterway values.

Appendix A of the WWMS describes the method used to divide the Wimmera CMA into 12 Waterway Management Units (WMU). Detailed information on each river reach which makes up a WMU has been gathered through literature reviews and field inspections. Tables summarizing the stability, ecological condition and estimated cost of works required for each reach are provided. This report aims to confirm and elaborate on the findings of the WWMS in relation to Reach 2 as defined in the Wimmera River Geomorphic Investigation. Reach 2 is wholly contained within Waterway Management Unit 1.

The Wimmera Water Quality Strategy

The aim of the Wimmera Water Quality Strategy is to improve the quality of river water so as to bring environmental, social and economic benefits to the region. Poor water quality has resulted in a significant number of blue green algae blooms in the past. Implementing the strategy could reduce total phosphorous levels in the Wimmera River by up to 42 tonnes per year (WCMA 2001).

The strategy is to be applied through a number of Programs. Of these, Program 7; Catchment and River Health Management, is most relevant to this report. Its

objective is to, "ensure that catchment and river health management in the region will result in improved water quality". This is to be achieved through:

- Waterway repair and maintenance;
- Flow regimes;
- Riparian management; and
- Catchment management.

It has been estimated that catchment wide implementation of these strategies could reduce total phosphorous input to the catchment by 24.1 tonnes per year.

The Wimmera River Geomorphic Investigation

The Wimmera River Geomorphic Investigation (WRGI) comprises a review and analysis of sediment processes within the Wimmera catchment, with a focus primarily on the Wimmera River. This report recommends that the following priorities, based on the principles of best practice catchment management, be applied:

- Preserve areas with near pristine values;
- Restore areas of high value;
- Rehabilitate areas that place other values at risk or provide good opportunity for restoring values; and
- Maintain degraded areas to prevent values declining to unacceptable levels.

Broadly examining the upper catchment areas, the Geomorphic Investigation found that some streams and tributaries are delivering high sediment loads to the Wimmera River. This excess sediment is threatening reaches harbouring rare geomorphic and ecological features. In particular the report found that Reaches 2, 4 and 6 are high priorities for management intervention.

With regard to Reach 2 the WRGI (ID&A 2002) noted the following Management Implications for Reach 2 and its tributaries.

Wimmera River

"The contemporary adjustments to geomorphic character that have occurred due to drainage works and subsequent gully erosion have not altered the geomorphic behaviour of this reach. Due to some of the reach boundary conditions, which have not changed since European settlement, this reach will naturally accumulate sediment and in some sense recreate the swampy environment possibly containing a Chain of Ponds. Working with these stream processes will be the most effective river rehabilitation strategy".


"Reaches 2.1 and 2.3 are intact fill, containing freshwater meadows and chain of ponds, protection of these reaches should be high priority for management." "....it is a high priority to ensure no further degradation of those geomorphically intact reaches, 2.1 and 2.3, occurs. High priority should also be given to the rehabilitation of reach 2.23, it is short, between reaches 2.1 and 2.3 and poses a threat to their status."

Tributaries

"Objectives for the management of the tributaries contain two categories:

- management for processes that impact on stream health and land management within the tributary system
- management for process that impact on the Wimmera River.

"Management should be directed at reducing the rate of sediment input from the upper catchment areas...by trapping sediment within the tributary system."



Relationships between reports used to compile the Wimmera River Waterway Action Plan for Reach 2.

River Health Assessment

Overview of Reach 2

The Wimmera River Geomorphic Investigation (IDA 2002) divided the Wimmera River into 20 management reaches based on geomorphic characteristics and behaviour. The reaches commenced at the upstream end of the Wimmera River and finished at Lake Hindmarsh.

Reach 2 is approximately 16 kilometres in length, commencing upstream of a significant freshwater meadow on Crown Land immediately upstream of Lower Wimmera Road. The reach finishes at the confluence of the Wimmera River and the Glenlofty Creek. The reach passes through agricultural land, predominantly used for grazing, and the township of Elmhurst. A number of named and unnamed tributaries join the Wimmera River within the reach. Named tributaries include:

- Tom the Tailor Creek
- Little Wimmera River
- Hickman Creek
- Rocky Creek
- Sandy Creek
- Glenpatrick Creek
- Nowhere Creek

(see Figure 1).

For most of its length, Reach 2 is within Crown Water Frontage. However given the swampy nature of much of the reach, there are significant waterway values on adjacent private property. There are 3 sections which are not on Crown Water Frontage;

- 1. a small section downstream of Lower Wimmera Road,
- 2. within the township of Elmhurst, and
- 3. approximately 2 kilometres upstream of the Glenlofty Creek.

Artificial channelisation, undertaken in the past, initiated channel incision resulting in the formation of a continuous, defined channel along the majority of Reach 2. The very upper parts of the Wimmera River (Reach 1) and the Little Wimmera River, which have intact chain of ponds, are the only sections unaffected by the deepening process.

Upstream of the Pyrenees Highway, a chain of ponds morphology is the dominant feature. The river alternates from shallow, swampy reaches with a non-defined channel, abundant instream vegetation and very little overstorey, to a stable incised channel with slow pools separated by long sections with abundant instream vegetation and patchy, narrow bands of overstorey riparian vegetation.

Swampy sections are very stable, heavily vegetated and provide good habitat to bird life and instream fauna. Incised sections that appear to be reverting to their original

form generally comprise long pools separated by longer sections of thick instream vegetation (usually phragmites and/or cumbungi).

Stock access is not restricted from all of this section, however it does not pose a major threat to stream health, as the type and thickness of vegetation and the extent and duration of inundation is a deterrent to stock. There is no evidence of stock significantly impacting on the physical characteristics of this reach although it is likely that they impact on water quality.

Willows and poplars dominate some of the incised reaches, reducing the abundance of aquatic plants, riparian diversity and in stream habitat. Willow roots in the stream are presently holding a number of small erosion heads. Whether the willows are preventing their upstream migration or in fact are the cause of them is difficult to determine (the only erosion heads noted upstream of the Highway were among willow roots except those that have already passed into the Hanging Swamp).

A concrete drop structure upstream of the Hickman Creek confluence, (approximately 5 km upstream of Elmhurst) marks a significant change from a poorly vegetated and incised reach to a swampy reach with abundant reeds and poorly defined channel. The structure was constructed in the 1960's in a joint effort between local Government and landholders to address channel incision in the Wimmera River. The structure was refurbished in 1990 by local landholders and in 2000 was again repaired by the Wimmera CMA. The structure is now a key asset of the Wimmera CMA.

In December 2001 Fisher Stewart Pty Ltd (on behalf of the Wimmera CMA) undertook an engineering survey of the Wimmera River between Elmhurst and the Hanging Swamp (Appendix B). Approximately 150 metres within Reach 2.2 was inaccessible. The results of the survey were incorporated into an assessment of Hanging Swamp (Appendix C). The survey of the Wimmera River is approximately 8.5 km in length. Cross sections were surveyed at an average interval of 250 m.

Assessment of the survey information indicates the following:

- The average bed grade between the concrete drop structure and the Hanging Swamp is 1 in 250 (0.004 m/m) which is also a low energy system but contains a pre European settlement channel form
- The average bed grade downstream of the concrete drop structure is approximately 1 in 330 (0.003 m/m) indicating a low energy fluvial system demonstrated by the accumulation of fine grained sediment within the active river channel.

Downstream of the Pyrenees Highway, the Wimmera River maintains a more open channel with larger flow capacity, and more overstorey vegetation but less instream vegetation. The overstorey vegetation, although still inadequate, provides a substantial portion of instream debris, which is required to maintain habitat and channel stability.

The Wimmera River at Elmhurst has undergone extensive infilling of the floodplain in this section which appears to have been exacerbated by the Avoca - Ararat Railway line at the downstream end of Elmhurst. The Elmhurst Landcare Group in conjunction with the Wimmera CMA carried out extensive waterway works in this section of the river in 1999/2000. Pool and riffle sequences were created and extensive weed control undertaken to improve the overall amenity of the area and create sediment traps.

Sandy Creek and the Glenpatrick /Nowhere Creek system are major tributaries which enter the Wimmera River at Elmhurst. Both systems have undergone incision in the past which has contributed sediment to the Wimmera River. Erosion processes are still active in the Glenpatrick and Nowhere Creeks. Incision is less active in Sandy Creek.

Native riparian vegetation is sparse along the length of Reach 2 and where it exists it is usually in narrow strips. This has resulted in poor shading and a low portion of instream debris to provide habitat. The abundance of instream debris improves downstream of the Elmhurst - Glenpatrick Road.

The main threats to river health upstream of the highway are bed instability, pest plants (willows, poplars, gorse), and bank instability and declining water quality due to stock access.

The main threats to river health downstream of the highway are pest plants (mostly gorse, some willows and poplars), stock access, lack of riparian vegetation and variable instream habitat.



Figure 2 Typical Freshwater Meadow upstream of Pyrenees Highway

Overview of Reach 2 tributaries

Little Wimmera River

The Little Wimmera River occurs within Crown Water Frontage before entering State Forest. The river is characterised by an upper and lower section separated by a private vehicle crossing off the Lower Wimmera Road. The upper section is an example of an intact chain of ponds reach in excellent condition. The lower reach is a well vegetated, incised reach that is reasonably stable although some small erosion heads are migrating towards the crossing. Stock access is limited although

riparian vegetation and fencing could be improved. The main management issues for the two reaches are control of the active headcuts that threaten the upper reach and improvement of riparian vegetation and instream habitat.



Figure 3 Upper section of Little Wimmera River in excellent condition

Tom the Tailor Creek

The creek, on private property, has incised up to three metres and more in some parts with vertical sides and localised instabilities. Previously active gully heads are currently stable and the creek itself is mostly stable. The biggest threat is from stock access and over grazing although a large portion of the creek is located within land used for tree plantations. Future logging operations may pose a threat if a vegetated buffer is not maintained between the logging and the stream banks. The main management objectives are to maintain creek stability and improve riparian vegetation to prevent impacts on downstream receiving reaches.



Figure 4 Tom the Tailor Creek, incised but stable - note plantation in the background

Hickman Creek

Hickman Creek, Rocky Creek and Sandy Creek all flow off granitic hills, have undergone gully erosion and are therefore likely to have delivered large quantities of sediment to the Wimmera River and its floodplain. Hickman Creek is on private property for all but a small section. The creek appears to have stabilised with good instream vegetation where it enters the Wimmera River. Monitoring of sediment inputs from the creek should be undertaken. The major landholder on Hickman Creek is currently investing significantly in fencing, revegetation and off stream watering along the creek.

Rocky Creek

Rocky Creek occurs on private property and is stable where it enters the Wimmera River. A concrete drop structure, approximately 100 metres from the Wimmera River confluence, has been incorporated into the road bridge on the Elmhurst – Beaufort Road. The structure has stabilised the creek immediately upstream of the road. There is, however, a large sediment slug, of unknown origin, in the Wimmera River at its confluence with Rocky Creek. Less than 1 kilometre upstream of the Elmhurst –Beaufort Road, Rocky Creek is highly degraded. Stock have unlimited access to the creek, there is little to no riparian vegetation and an active head scour is working its way up the creek.

Sandy Creek

Sandy Creek has undergone incision in the past but is now stable. There are minor instabilities in the upper reaches but sediment is not transported to the Wimmera River. Upstream of Sandy's Lane much of the creek occurs within or adjacent to the Pyrenees Hwy road reserve and thus is well vegetated. Downstream of Sandy's Lane the creek is within Glenpatrick Streamside Reserve and is similarly well vegetated. Fencing of private property downstream of Glenpatrick Streamside

Reserve has resulted in a stable, well vegetated creek although overstorey vegetation and recruitment is sparse. Approximately 100 metres upstream of Wiltshire's Lane to its confluence with the Wimmera River the creek is unfenced and in poor condition. Whilst the creek is stable, stock access is unlimited and gorse and rabbits are prevalent.

Glenpatrick/Nowhere Creek

The lower reaches of Glenpatrick and Nowhere creeks occur within Crown Water Frontage. This creek system has also undergone substantial gully erosion and incision. Continual filling of the floodout zone through increased sedimentation rates has resulted in continued attempts to maintain channel capacity through excavation. The excess sediment inputs from gully erosion in the upper catchment exacerbate this process and thus pose land use hindrances. Management should be directed at reducing the rate of sediment input in the upper catchment areas by trapping sediment within the tributary system (ID&A, 2002).

Other tributaries

The last major right bank tributary in Reach 2, shortly upstream of the Elmhurst Landsborough Road, has experienced severe gully erosion that is contributing substantially accelerated rates of sediment input to the Wimmera River (ID&A, 2002).

Left bank tributaries between Elmhurst and the end of Reach 2 have undergone incision in the past. Head erosion at the upstream end of these tributaries is still active but appears to not be contributing sediment to the Wimmera River. The Pyrenees Highway and the Ararat – Avoca Railway line, which are approximately 100 metres from the Wimmera River in this section, are acting to trap sediment before it enters the river. The greatest threat to the stability of these areas is from works in road and railway reserves.

Overview of Management Reaches

The Wimmera River Reach 2 has been divided into 4 management reaches based on the Wimmera River Geomorphic Investigation (WRGI 2001) and field inspection (Appendix D)

- Reach 2.1 "Hanging Swamp" to Lower Wimmera Road
- Reach 2.2 Lower Wimmera Road to end of poplars
- Reach 2.3 End of poplars to Drop Structure upstream of Hickman's Creek
- Reach 2.4 Drop Structure upstream of Hickman's Creek to Glenlofty Creek

Recommendations for management activities in each of the reaches is detailed in Appendix A. Chainages shown below for reaches are based on the Plan of Survey & Cross Sections, Wimmera River Elmhurst (Appendix B).

Reach 2.1 - "Hanging Swamp" to Lower Wimmera Road (Survey Chainage CH: 7900 - CH: 8400)

The sub-reach commences immediately upstream of the freshwater meadow within State Forest, upstream of Lower Wimmera Road, The confluence of the Little Wimmera River and Tom the Tailor Creek with the Wimmera River is the end of the reach. The reach represents the upper-most sub-reach of Reach 2.

The dominant feature of the sub-reach is the freshwater meadow. Due to its perched nature, the freshwater meadow has been colloquially termed "Hanging Swamp"

Hanging Swamp is in excellent condition although it is currently under threat from headward erosion in the Wimmera River. Multiple erosion heads have already progressed into the downstream edge of the swamp and are migrating upstream along different paths. Stock have no access to the swamp. The assessment of Hanging Swamp detailed the following.

- "An erosion head of approximately 3.5 m drop is located immediately downstream of the Hanging Swamp
- Approximately 3.0 m of this drop is located within the first 20 m downstream of the Hanging Swamp
- An erosion head of similar size is located within the first 100 m of the Little Wimmera River, downstream of a farm access crossing"
- "....Under existing conditions the Hanging Swamp and Little Wimmera River are not at immediate threat of wide spread damage: incision processes are occurring at a slow rate."
- "....The willows downstream of the Hanging Swamp currently have a beneficial value in stabilising a small erosion head. If this erosion head were to join with the erosion head at the Hanging Swamp then the rate of incision could increase."

A recently established blue gum plantation is located adjacent to the Hanging Swamp. Future plantation activities may impact upon and pose a threat to the swamp.

Immediately downstream of Hanging Swamp instream willows are growing almost to the confluence with Tom the Tailor Creek. The willows are effectively stopping the progression of further erosion heads from reaching the Hanging Swamp.



Figure 5 Willows holding erosion heads immediately downstream of Hanging Swamp

Immediately below its confluence with Tom The Tailor Creek the Wimmera River is incised but stable due to the thick growth of phragmites and some cumbungi in the streambed. A culvert on the Lower Wimmera Rd provides further stability to the stream bed due to its backwater effect. The stream is fenced and has been revegetated on both banks downstream of the culvert. The banks are quite steep but reasonably stable due to the existing riparian vegetation and lack of stock access.

Reach 2.2 - Lower Wimmera Road to end of poplars

(Survey Chainage CH: 6950 – CH:7900)

Sub-reach 2.2 is a short reach of approximately 900 metres. It has Tom the Tailor Creek and the Little Wimmera River as its major tributaries at the upstream end of the reach. The WRGI described the sub-reach as "....clearly a man-made drain that has been lined with exotic tress (primarily willow)".

The sub-reach is incised but does not have high banks and its riparian zone is dominated by exotic vegetation in the form of willows and poplars. There are some small patches of native vegetation providing instream and bank habitat although the riparian zone along the entire length is very narrow. Fencing exists along the right bank, albeit too close to the river, for the entire length although it has been damaged in places due to fallen trees. There is no fencing along the left bank for the entire reach. Willow roots are holding some erosion heads upstream of the plantation although the reach is generally stable. Instream habitat is limited.

Tom The Tailor Creek has incised up to three metres and more in some parts with vertical sides and localised instabilities. Previously active gully heads are currently stable and the creek itself is mostly stable. The biggest threat is from new instabilities as a result of stock access and over grazing although a large portion of

the creek is located within land used for tree plantations. Creek crossings may be required in the plantation area when operations begin and this may pose a threat to stream stability.

The upstream section of the Little Wimmera River is an example of a chain of ponds reach in excellent condition. The lower section of the river is an incised reach that is reasonably stable although some small erosion heads are migrating towards a private crossing. Instream vegetation is very good and stock access is limited although riparian vegetation and fencing could be improved.

Reach 2.3 - End of poplars to Drop Structure upstream of Hickman's Creek

(Survey Chainage CH: 5000 - CH: 6950)

Reach 2.3 sees the river returning to a stable floodplain reach. A large concrete drop structure marks the downstream end of the reach where the stream changes dramatically from a heavily vegetated swamp to a deeply incised channel with little instream and riparian vegetation.

The upper section of the reach is generally stable and is dominated by instream vegetation of phragmites and cumbungi. There are very few trees with a consequent low diversity of instream habitat. Fencing exists in places although it is not strategically positioned for protection of the river. Stock access is of concern where banks are more vulnerable and slightly unstable. For the majority of the reach stream stability is not affected by stock access although water quality may be affected. The river appears to divide into two or more channels through a swampy section and three or four young willows are growing in the middle of the stream.

In the mid sections the reach becomes channelised with willows along the majority of the length and almost no native overstorey. Erosion heads are being held by willow roots (behind the Keith household). Discontinuous fencing on both banks is ineffective at restricting stock access however, the nature of the stream (spiny rushes and often inundated with water) is a deterrent to stock.

In the lower sections it is very stable and heavily vegetated with instream reeds, rushes on the floodplain and very little overstorey as the stream turns back to a swamp-like waterway. Although it is fenced off in the lower parts stock can access the stream.

The end of the reach is defined by a drop structure upstream of the confluence of Hickman's Creek. The history of the structure is described above.



Figure 6: Drop structure on Wimmera River upstream of Hickman Creek

Reach 2.4 - Drop Structure upstream of Hickman's Creek to Glenlofty Creek

(Survey Chainage CH: 0 – CH: 5000 and length of river downstream of start of survey point)

The Wimmera River downstream of the drop structure has a clearly defined channel due to past incision. Instream and riparian vegetation is patchy although gradually improving downstream of the drop structure. The bed and banks are generally stable although stock access impacts on bank stability and vegetation establishment.

Fencing is well underway with some sections completed and others with pegs in place marking future fencing alignments. Unfortunately some of the fences are too close to the bank to provide any long-term benefits as there is no room for riparian vegetation to establish. There are some good patches of instream habitat provided by reeds and LWD, however, these are often separated by large lengths of uniform channel with no riparian vegetation.

The most upstream sighting of gorse is near the confluence with Rocky Creek.



Figure 7 Looking downstream from concrete drop structure

Downstream of the confluence with Rocky Creek there is another swampy section that is stable, well vegetated and in good overall condition. Small patches of gorse, coming from the upstream reach, some recently planted willows and blackberry are also present. Rabbits are evident although they do not appear to be a major problem. There is little overstorey vegetation although with recent fencing on both sides eucalypts are beginning to regenerate naturally. Just upstream of the Pyrenees Highway (500m) marks the end of the swampy section and the beginning of the stream channel becoming more defined.

To a point approximately 500m upstream of the Elmhurst Landsborough Road there are short sections that are dominated by instream vegetation and little overstorey, however, the stream channel remains defined throughout. The river is fenced on both sides although the fencing is often too close to the bank edge to provide sustainable benefits. Native riparian vegetation is almost continuous but is in very narrow bands or only on one bank. Gorse is a major weed problem, particularly between the railway line and the confluence with Sandy Creek. There is a good variety of instream habitat provided by snags, pools and reeds in sections of the reach.

Downstream to the confluence with Glenlofty Creek the stream is incised with sediment in the streambed and banks are collapsing due to cattle access. Isolated Red gums appear along the banks and in the streambed. Gorse is beginning to take over in the riparian zone. Instream habitat is limited and water quality is very poor due to the sediment filled bed, cattle access and no LWD.



Figure 8 Gorse on banks and direct stock access at the downstream end of Reach 2

References

DNRE (Department of Natural Resources & Environment), 2002, Draft Victorian River Health Strategy, Catchment & Water division DNRE, Melbourne, Australia.

Earth Tech Engineering, 2002, Habitat Restoration Project for the Glenelg River at Harrow; Conceptual Design, Earth Tech, Hamilton, Victoria.

Land Technology, 2000, Concongella Landcare Group, Astons Scour Group: Catchment Management Plan, Astons Scour, Land Technology Pty Ltd, Horsham, Victoria.

Rutherfurd, I D, Jerie K & Marsh N, 2000, A Rehabilitation Manual for Australian Streams Volume 2, Co-operative Research Centre for Catchment Hydrology, Department of Civil Engineering Monash University, Melbourne, Victoria.

Treadwell S (ed), 1999, 'Managing snags and Large Woody Debris' in S.Lovett and P.Price (eds), Riparian Land Management Technical Guidelines, Volume two: Onground Management Tools and Techniques, Land and Water Resources Research and Development Corporation, Canberra, pp.15-22

WCMA (Wimmera Catchment Management Authority), 1999, Wimmera Waterways Management Strategy, WCMA, Horsham, Victoria.

WCMA (Wimmera Catchment Management Authority), 2001, Wimmera Water Quality Strategy, WCMA, Horsham, Victoria.

ID&A, 2002, Wimmera River Geomorphic Investigation, ID&A, Melbourne, Australia.

Appendix A: Proposed Program of Activities for Reach 2

Reach 2.1 - "Hanging Swamp" to Lower Wimmera Road

- Control of the erosion heads that threaten Hanging Swamp
- Prevent upstream migration of the erosion heads (and hence resultant sediment release downstream)
- Prevention of the erosion heads within willows moving upstream and into the Hanging Swamp
- Improvement of the instream habitat and riparian vegetation values

Recommended actions	Priority
Monitor the rate of movement of the erosion heads through the swamp using ground survey (including pegs in ground, photos, and measurement)	High
Undertake grade control if required	
Investigate future activities in adjacent plantation to determine possible impacts on swamp	
Monitor movement of erosion heads among exotic vegetation	
Selective poisoning/removal of willows in reach pending results of monitoring. Any actions here will depend on outcomes of monitoring heads on the edge of the swamp	
Fence both sides of river from Hanging Swamp to the Little Wimmera Road crossing (approximately 225m) if stock have access	
Monitor for stability and pest plants from upstream in short section below confluence with Tom The Tailor Creek	Low
Determine whether stock access the section upstream of the culvert and fence if required.	

Reach 2.2 - Lower Wimmera Road to end of poplars

Management Objectives

- Improve riparian zone and instream habitat values
- Maintain stream stability

Recommended actions	Priority
Monitor and control, if necessary, erosion heads currently located among some willow roots	Medium
Poison and follow-up removal of willows and poplars through reach over approximately 400m.	
Install fencing on both sides of river to restrict stock access	
Fence out the left bank (400m) and repair damaged sections of the right fence	
Longitudinal bed survey	
Monitor erosion heads and implement stabilisation measures where required.	

Tom The Tailor Creek

- Maintain and improve present stream stability
- Reduce stock access or improve management of grazing within riparian zone.

Recommended Actions	Priority
Fence and revegetate right and left banks (approximately 5300m).	Low
Improve grazing management through landholder consultation	

Little Wimmera River

- Monitor and control erosion heads
- Improvement in riparian vegetation and instream habitat

Recommended Actions	Priority
Monitor progress of erosion heads	Low
Fence and revegetate the left bank above private crossing (approximately 1470m).	
Revegetate banks below private crossing to confluence with Wimmera River (approximately 70 metres. Banks already fenced)	

Reach 2.3 - End of poplars to Drop Structure

- Improve riparian zone and instream habitat values
- Maintain bed stability
- Maintain condition of drop structure

Recommended actions	Priority
Within the section dominated by willows and Hawthorn, remove exotic vegetation and fence and revegetate (approximately 600m).	Medium
Manage erosion heads among the willow roots to ensure they don't progress into the stable upstream section of reach	
Fencing and revegetation at start of reach to protect vulnerable banks (approximately 190m either side).	Low
Fence and revegetate other unfenced sections of river (300m right bank, 600m left bank)	

Reach 2.4 - Drop Structure upstream of Hickman's Creek to Glenlofty Creek

- Link up high value swampy reaches
- Protect the function of the drop structure, which provides stability to the upstream reach
- Increase abundance of riparian and instream vegetation and width of riparian zone
- Control and prevent the spread of exotic vegetation
- · Control pest animals

Recommended actions	Priority
From drop structure to downstream end of section where river reverts to swamp complete fencing on both banks (approximately 1100m total), increasing width	High
Revegetate left and right banks.	
Remove exotic vegetation from river and Rocky Creek confluence (approximately 200m)	High
Commencing 1100 metres upstream of Elmhurst – Glenpatrick Road Bridge	High
Remove gorse (1100m)	
Revegetate to railway line (some parts already done)	
Fence both banks between railway line and Elmhurst Glenpatrick Rd (approximately 200m either side). Existing fencing on right bank is to be replaced.	High
Between Eyrie Stud boundary and Landsborough Road	High
 Fence gaps and revegetate on left and right banks, approximately 300m 	
Approach landholders to increase the setback of current fencing along the river - if not the permanent fencing at least the temporary fencing	
Remove exotic vegetation (some willows)	

Recommended actions	Priority
Remove exotic vegetation from river in swampy section downstream of Rocky Creek confluence to 500 m upstream of Pyrenees Hwy (approximately 750m)	Medium
Remove exotic vegetation and fence left bank and revegetate both banks upstream of Pyrenees Hwy (170m)	Medium
Fence and revegetate right bank downstream of Pyrenees Hwy (470m)	
Remove exotic vegetation downstream of Pyrenees Hwy (470m)	
From Elmhurst Glenpatrick Rd Bridge to downstream property boundary of Eyrie Stud (ex deer farm)	Medium
Fence and revegetate both banks (750m either side), and	
Re-introduce LWD	
Revegetate left and right banks (approximately 380m) from downstream of property boundary of Eyrie Stud	Medium
Continue gorse control in above section	
From just upstream of Landsborough Road to confluence with Glenlofty Creek	Medium
Remove gorse	
Fence and revegetate left and right banks (approximately 1500m)	
Re-introduce LWD for habitat	
Investigate provision of fish passage past the drop structure	Low

Issues Arising From the Works Program

Instream Reed Growth

Cumbungi and phragmites are the two main species of reeds that occur throughout the Wimmera catchment area. The growth of these reeds in the stream bed is essential to stream stability and provides a means of trapping and holding sediment in the reach. Although sediment trapping is essential for the rehabilitation of Reach 2, and for the protection of Reach 3, landholders may have concerns that trapped sediment is filling waterholes used for stock watering. Other landholder perceptions are that reed growth leads to increased flooding and an increased fire hazard.

Loss of Stock Watering Holes

Without intervention to maintain a channelised stream, the Wimmera River will, due to geomorphic processes, revert to its original chain of ponds nature (ID&A, 2002). This process is evident in Reach 2. Low velocity flows result from a decrease in streambed gradient and reduced channel capacity. During low flows reed beds throughout the reach are trapping and holding sediments, leading to the formation of a chain of ponds sequence. Without this trapping action by reeds, an open channel with a low gradient will fill with sediment, leading to a homogenous streambed lacking waterholes and geomorphic diversity. Along some reaches the works program outlined in Appendix A calls for stock access to be denied at all times. In such cases it is recommended that off-stream watering points be implemented.

Increased Flooding Due to Reeds

Low flows with an accompanying decrease in flow velocity lead to an increase in the deposition of sediment from erosion processes upstream. This in turn leads to a decrease in a river's ability to contain higher flow events. Low flow velocities and shallow flow depths contribute to an increase in reeds within the affected reach. In many cases reed growth is a symptom of a channel's decreased capacity to carry higher flows. Landholder perception, therefore, is that reed growth is leading to increased flooding.

As the upper reaches of the Wimmera River originally assumed a low flow chain of ponds morphology, its ability to carry higher flows was limited. Higher flows readily spread onto the land alongside the river. Without constant and costly mechanical intervention to maintain an open channel, the river will attempt to resume a similar morphology to that which it had prior to European intervention (ID&A, 2002). Therefore increased flooding is to be expected, due to decreased channel capacity, whether or not reeds are present in the stream bed.

Increased Fire Hazard Due to Reeds

Landholders may be concerned that a fire is able to spread faster or cross a waterway due to burning reeds. The works program calls for some sections of stream to be kept free of stock at all times. This is to enable reed growth for sediment trapping and bed stability purposes. Although little can be done to reduce the fire hazard in such cases, the length of stream to which stock access is excluded is relatively small.

In other well-vegetated areas where stock access does not pose a major threat to stream health, limited access will be possible. Due to the ephemeral nature and dense vegetation of chain of ponds sections, stock access can be timed so that reeds are grazed to reduce the fire hazard while not affecting their ability to trap

sediment on regrowing. It is suggested that reeds are grazed in late winter to early spring.

Increased Flooding Due to Large Woody Debris

Large Woody Debris (LWD) consists of the fallen trunks and branches of trees which occupy the riparian zone. LWD is recognised as an important structural and ecological component of many stream environments, and as such the objective of stream management projects is to manage snags and LWD in such a way that the ecological health of rivers is enhanced at the same time that risks of flooding and streambank erosion are diminished (Treadwell, 1999).

Past works to remove LWD were undertaken in the belief that trees lying in the river contributed to increased flooding of upstream areas. Evidence from research now suggests that removing single logs from a stream will have little effect on flood stage (Rutherfurd et al. 2000). Recent computer modelling (Earth Tech. 2002) has clearly shown that the re-introduction of LWD to a reach of the Glenelg River at Harrow will have a minimal effect on flood height. With an average log distribution density of 15 logs per 100m of stream bed, the maximum average increase in water level of 0.11 metres during a 1 in 2 year flood event was shown to occur

By re-introducing LWD in a strategic manner, it is proposed that, through the creation of hydraulic and depth diversity, significant and rapid increases in the ecology of the stream will occur (Gippel et al, 1998), with an almost insignificant risk of increased flooding.

Appendix B: Plan of Survey and Cross Sections, Wimmera River Elmhurst

Appendix C: Hanging Swamp Stability Assessment

Appendix D: Wimmera River Reach 2, Landholder Property Boundaries



Wimmera Catchment Management Authority

Hanging Swamp Stability Assessment

Job 2901049

February 2002

APPROVED	CHECKED
DATE	DATE

© Earth Tech Engineering Pty Ltd

All Rights Reserved. No part of this document may be reproduced, transmitted, stored in a retrieval system, or translated into any language in any form by any means without the written permission of Earth Tech Engineering Pty Ltd.

Intellectual Property Rights

All Rights Reserved. All methods, processes, commercial proposals and other contents described in this document are the confidential intellectual property of Earth Tech Engineering Pty Ltd and may not be used or disclosed to any party without the written permission of Earth Tech Engineering Pty Ltd.

Earth Tech Engineering Pty Ltd

ABN 61 089 482 888 Head Office 71 Queens Road Melbourne VIC 3004 Tel +61 3 **8517 9200**





Wimmera Catchment Management Authority Hanging Swamp Stability Assessment

Job 2901049

Contents

Introduction	1
Stability Assessment	2
Site Inspection	
Engineering Survey	
Hydraulic Analysis	
Conclusions and Recommendations for Management	6
Conclusions	
Recommendations	

Introduction

This report details the stability assessment for two sections of waterway:

- The Hanging Swamp, a section of the Wimmera River which commences upstream of Lower Wimmera Road, Elmhurst and continues for approximately 2 km.
- The Little Wimmera River, a tributary of the Wimmera River, which joins the Wimmera River just downstream of Lower Wimmera Road, Elmhurst.

These sections of waterway are freshwater meadows or chain of ponds type streams. They are a rare geomorphic unit that is poorly represented throughout Australia.

Drainage works have lead to the incision of the Wimmera River downstream of these reaches. The incision process has progressed upstream and large erosion heads now form the downstream boundaries of the Hanging Swamp and Little Wimmera River.

Stability Assessment

Site Inspection

The Hanging Swamp and Little Wimmera River were initially inspected by ID&A (now Earth Tech Engineering) as part of the Wimmera River Geomorphic Investigation. This inspection identified the high values of these reaches and the incision processes threatening their stability.

Further inspections were undertaken in December 2001 to direct the survey party in the collection of data and again in January 2002 to assess the survey information.

Both of these waterways are densely colonised by in-stream vegetation such as phragmites, typha and sedges. A large fall in bed elevation (erosion head) is clearly visible at the downstream boundary of the Hanging Swamp. It is apparent that the dense vegetation has resisted and continues to resist the upstream progression of incision processes.

Mature willows in the incised section of the Wimmera River downstream of the Hanging Swamp form a useful reference point to indicate the rate of incision processes. The presence of these willows suggests the erosion heads of the Hanging Swamp have progressed upstream by a maximum of 20 m in the last 20 -50 years.

A large fall in bed elevation occurs in the Little Wimmera River in its last 100 m before joining the Wimmera River. Unlike the Hanging Swamp, this fall in bed elevation is gradual. It is apparent that the vehicle crossing approximately 100 m upstream of the Little Wimmera River/Wimmera River junction is also assisting in preventing the upstream progression of the incision processes.

Plates 1 to 4 show various features of the Wimmera and Little Wimmera Rivers.

Engineering Survey

Fisher Stewart Pty Ltd (on behalf of the Wimmera CMA) undertook an engineering survey of the Wimmera River between Elmhurst and the Hanging Swamp in December 2001. This reach of the Wimmera River is approximately 8.5 km in length. Cross sections were surveyed at an average interval of 250 m.

Assessment of the survey information indicates the following:

- The average bed grade downstream of the Wimmera River concrete drop structure is approximately 1 in 330 (0.003 m/m)
- The average bed grade between the Wimmera River concrete drop structure and the Hanging Swamp is 1 in 250 (0.004 m/m)
- An erosion head of approximately 3.5 m drop is located immediately downstream of the Hanging Swamp
- Approximately 3.0 m of this drop is located within the first 20 m downstream of the Hanging Swamp
- An erosion head of similar size is located within the first 100 m of the Little Wimmera River, downstream of a farm access crossing



Plate 1
Wimmera River, Hanging Swamp
looking upstream near
downstream boundary



Plate 2
Little Wimmera River looking
upstream near junction with
Wimmera River



Plate 3Wimmera River, Hanging Swamp



Plate 4
Wimmera River just downstream
of Hanging Swamp showing
willows

Hydraulic Analysis

The rational method for Victoria presented by Australian Rainfall and Runoff (1998) has been utilised for flow estimation.

Stream flow calculations can be seen in Appendix A. Flow estimates for the Hanging Swamp and Little Wimmera River are shown in **Table 1**.

Table 1: Flow Estimates

Catchment	Area (km²)	Design Flows for ARI in Years (m ³ /s)							
	(KIII)	1	2	5	10	20	50	100	
Little Wimmera River at Wimmera River Junction	9.1	2.21	3.66	5.97	7.81	10.3	13.9	17.4	
Wimmera River Upstream of Tom-the- Tailor Creek	12.8	2.83	4.68	7.61	9.94	13.1	17.6	22.1	
Wimmera River Upstream of Little Wimmera River	40.4	6.66	11.0	17.8	23.1	30.3	40.6	50.7	
Wimmera River Downstream of Little Wimmera River	49.5	7.79	12.9	20.8	27.0	35.4	47.4	59.1	

Together with survey information, this flow data was utilised to construct a HEC-RAS hydraulic model of the Wimmera River Geomorphic Reach 2.2 (i.e. the incised reach downstream of the Hanging Swamp).

Stream power is a tool that can indicate the potential of a watercourse to undergo change. Field research has shown that:

- Waterways with bank full stream power less than 35 N/ms are unlikely to undergo significant change
- Waterways with bank full stream power between 35 and 100 N/ms are likely to undergo minor change, such as localised bank erosion
- Waterways with bank full stream power in excess of 100 N/ms are likely to undergo major change, such as bed deepening and widening.

These change processes can be resisted by bedrock, coarse bed sediment and dense vegetation.

Table 2 displays stream power estimates for bank full conditions.

These results indicate that the reach is unlikely to undergo major change. Cross section 8163.13 is protected from significant change by the presence of willows. Bank erosion could be expected at cross sections 7968.72 and 7744.18. Instream vegetation may resist this process.

Table 2: Stream Power Estimates

Cross Section Chainage (m)	Cross Section Description	Bankfull Flow ARI (years)	Bankfull Stream Power (N/m s)	2 year Stream Power (N/m s)	50 year Stream Power (N/m s)
8245.25	Just downstream of Hanging Swamp	> 100	8	9	8
8163.13	Just upstream of Tom- the-Tailor Creek junction	>100	82	65	74
7968.72	Just downstream of Little Wimmera River junction	> 100	79	27	64
7744.18	Wimmera River	< 50	110	60	110
7180.16	Wimmera River	< 1	9	9	40
6918.14	Start of reach 2.3	< 1	17	17	58

Conclusions and Recommendations for Management

Conclusions

The site, survey and hydraulic assessments indicate the following:

- A 3.0 m erosion head is present at the downstream boundary of the Hanging Swamp
- It appears that the rate of progression of this erosion head is less than 1 m per year
- A small erosion head is held within the willows immediately downstream of the Hanging Swamp
- Stream power within the incised reach of the Wimmera River downstream of the Hanging Swamp is of a magnitude such that significant bed deepening and channel enlargement is not expected
- A large erosion head is present within the last 100 m of the Little Wimmera River. This erosion head is not progressing at a significant rate

Recommendations

Under existing conditions the Hanging Swamp and Little Wimmera River are not at immediate threat of wide spread damage: incision processes are occurring at a slow rate.

However, these waterways are at threat from catastrophic events such as bushfire followed by flood. Under such a scenario the stabilising effects of vegetation may be lost and boundary conditions will lead to instability. The likelihood of this occurrence is low and the extent of damage is difficult to predict.

Works to increase the stability of these waterways could be undertaken. A number of options have been considered. Structures located downstream of the reaches would rely on a sediment supply to be effective. The intact fresh water meadows act as sediment traps meaning little sediment would be supplied to fill the bed behind the structures.

Construction at the downstream boundary of the intact reaches would involve their disturbance and possibly the destabilisation of the accumulated sediments on which they are formed.

Each of the options considered would involve risks that are considered greater than those currently faced.

It is therefore proposed that no works be undertaken at this point in time. The rate of incision should be monitored and works reconsidered if the rate of incision increases significantly.

The willows downstream of the Hanging Swamp currently have a beneficial value in stabilising a small erosion head. If this erosion head were to join with the erosion head at the Hanging Swamp then the rate of incision could increase.

If these willows are propagating and require removal then the stabilisation of the site should be reconsidered.

Appendix 1 – Design Flow **Calculations**

Flow Calculations using Rational Method

Design Rainfall Parameters (A	۹RR ۱	/ol 2)
-------------------------------	-------	--------

1 hour duration / 2 year average recurrence interval	² I ₁	19.00mm/h
12 hour duration / 2 year average recurrence interval	$^{2}I_{12}$	3.50mm/h
72 hour duration / 2 year average recurrence interval	² I ₇₂	1.00mm/h
1 hour duration / 50 year average recurrence interval	⁵⁰ l ₁	42.00mm/h
12 hour duration / 50 year average recurrence interval	⁵⁰ l ₁₂	7.00mm/h
72 hour duration / 50 year average recurrence interval	50 I $_{72}$	1.90mm/h
Average Regional Skewness	G	0.30
Geographical Factor for a 6 minute, 2 year ARI	F2	4.37
Geographical Factor for a 6 minute, 50 year ARI	F50	14.85

Runoff Coefficient (ARR, Vol 2, Figure 5.3b, page 107)

Runoff coefficient for ARI 10 years C ₁₀	0.15%
---	-------

Frequency Factors (ARR, Vol 1, Table 5.4, page 103)

Frequency Factor for 1 year event	FF_1	0.60
Frequency Factor for 2 year event	FF_2	0.75
Frequency Factor for 5 year event	FF ₅	0.90
Frequency Factor for 10 year event	FF ₁₀	1.00
Frequency Factor for 20 year event	FF ₂₀	1.10
Frequency Factor for 50 year event	FF ₅₀	1.20
Frequency Factor for 100 year event	FF ₁₀₀	1.30

Runoff Coefficients (C₁₀ x FF)


Runoff coefficient for 1 year event	C_1	0.090 %
Runoff coefficient for 2 year event	C_2	0.113 %
Runoff coefficient for 5 year event	C_5	0.135 %
Runoff coefficient for 10 year event	C_{10}	0.150 %
Runoff coefficient for 20 year event	C_{20}	0.165 %
Runoff coefficient for 50 year event	C ₅₀	0.180 %
Runoff coefficient for 100 year event	C ₁₀₀	0.195 %





Catchment	Area (km²)	Time o	f Conc.	Design Flows (m³/s) for ARI in Years						
	(KIII)	Hours	Mins	1	2	5	10	20	50	100
1	9.1	1.76	106	2.21	3.66	5.97	7.81	10.3	13.9	17.4
2	12.8	2.00	120	2.83	4.68	7.61	9.94	13.1	17.6	22.1
3	40.4	3.10	186	6.66	11.0	17.8	23.1	30.3	40.6	50.7
4	49.5	3.35	201	7.79	12.9	20.8	27.0	35.4	47.4	59.1


Catchment Areas

- Little Wimmera River at Wimmera River Junction
- 2 Wimmera River Upstream of Tom-the-Tailor Creek
- 3 Wimmera River Upstream of Little Wimmera River
- 4 Wimmera River Downstream of Little Wimmera River









GEOFF VIETZ I.D. & A. MELBOURNE OFFICE 71 QUEENS ROAD MELBOURNE PRINCIPAL DATUM RL281 CENTRELINE CHAINAGE DATUM RL277 DATUM RL285 CHAINAGE CHAINAGE CENTRELINE APPROX 42m SOUTH FROM SOUTHERN FENCE LINE OF McKAY STREET ROAD RESERVE 0.000 290.706 600.000 294.575 \$200.000 | 298.465 38.314 290.632 DEEP WATER HOLE 237.999 298.800 656.294 294.416 \$257.758 298.872 79.482 290.708 687.307 294.593 292.234 111.285 290.179 3318.594 720.828 294.47 345.956 298.89 183.397 290.048 \$398.469 298.830 206.946 290.447 821.809 294.703 240.238 290.536-245.078 290.844-3444.961 299.29 275.621 290.557 1876.517 294.949 288.579 290.976 298.407 290.966 1907.011 294.905 317.337 290.410 523.256 299.65 329.941 291.111 350.896 290.619 3551.476 299.670 3551.496 299.670 955.065 295.197 374.432 382.692 290.140 290.342 599.698 299.910 999.004 295.262-2000.000 295.254-416.871 290.738 299.897 438.195 291.375 670.750 300.03 485.522 291.315 692.322 298.919 500.000 291.056 511.243 290.855 2108.564 | 295.632-2108.674 | 295.631-3717.383 299.18 525.230 291.080 730.709 299.995 3750.945 3761.851 548.449 291.316 154.055 295.265 575.900 291.76 185.977 295.95 592.271 290.395 797.502 300.30 611.541 291.190 212.495 295.820 827.024 300.446 241.422 295.41 649.728 291.043 865.363 300.722 670.388 291.024 2270.651 296.00 698.358 291.33 305.204 296.09 3915.309 300.57 2324.517 2329.679 2329.679 2342.695 2350.203 2350.203 2354.419 2368.740 296.513 725.553 291.716 940.850 300.947 757.955 291.156 763.749 290.529 DEEP WATER HOLE 978.734 300.74 789.398 290.844 394.823 296.626 4000.000 4007.323 4012.939 300.870 300.913 300.954 CONCRETE FORD 416.700 296.818 824.827 291.697 2432.560 296.758-2432.715 296.758-2446.380 296.562-2458.911 296.659-1035.416 300.293 844.374 292.083 859.231 291.75 300.65 4060.641 2479.538 296.732 2489.881 296.335 2500.000 296.245 1077.423 301.076 879.934 291.343 DEEP WATER HOLE 108.243 300.997 915.380 291.055 520.365 296.065 2539.666 296.341 4161.891 300.994 968.272 BRIDGE PYRENEES HIGHWAY 2580.181 296.454 1201.382 301.287 4216.054 2617.854 296.45 040.805 292.230 4243.941 301.007 292.629-292.496-291.614-291.071-292.460 659.008 296.51 Datum
Horizontal 1:2500
Vertical 1:250 1639.006 236.310 1676.846 297.043 1688.016 297.268 1698.016 297.274 1699.7617 297.744 1799.7617 297.744 1799.7617 297.748 1714.020 297.038 1714.020 297.038 1714.020 297.038 1714.020 297.038 1714.020 297.038 1715.090 297.039 1726.1617 297.487 1749.781 297.487 1757.083 297.279 1755.171 296.170 1793.274 296.712 1805.276 296.745 1810.991 297.413 267.563 301.347 286.464 301.583 300.283 301.658 1102.426 291.618 4313.334 300.872 1322.972 301.245 128.572 292.85 4341.095 301.580 4352.199 301.739 1150.203 292.692 166.186 292.226 DEEP WATER HOLE HICKMAN CREEK 178.065 1182.753 1194.749 292.301 293.079 292.701 4387.016 301.990 1416.817 301.71 223.877 292.791 2831.082 297.574 437.595 302.096 2848.236 297.660 264.793 291.880 SURVEY & MAPPING GROUP GEELONG. Ph (03) 52 264200 882.599 297.732 Fisher Stewart 900.377 297.622 299.677 293.507 4500.000 302.079 4503.322 302.070 2915.625 297.766 326.257 293.717 A NEWMAN R HUNTER 1340.557 293.377 1352.343 292.245 1362.904 293.287 944.528 297.813 1543.246 302.326 966.059 297.938 570.905 Ą 훘 992.243 | 297.991 000.000 | 298.065 396.723 293.796 1: 2500 4602.553 302.833 4610.761 302.124 4617.912 302.633 1:250 1413.010 293.972 10/01/02 029.529 298.199-4637.107 302.70 450.292 294.020 658.433 302.515 069.633 298.340 DEEP WATER HOLE **Drawing No. 1701577-G2**Sheet No. 1 of 2 1478.361 294.121 679.743 302.926 LONGITUDINAL SECTIONS CH 00 - 4800m WIMMERA RIVER ELMHURST Sheet No. 1 of 2

© Earth Tech Engineering Pty Ltd ABN 61 ع الم 088.346 298.277 500.000 294.217 502.838 294.230 3110.268 298.290 723.379 303.009 3125.011 298.447 8 허 4750.041 303.120 3156.934 298.579-3166.437 298.180-565.232 294.342 DEEP WATER HOLE 1778.019 303.182 594.093 294.611-600.000 294.575-3192.080 297.178 3193.817 298.410 200.000 298.465 800.000 303.371 1701577-G2.dwg A1 Rev

PRINCIPAL
GEOFF VIETZ
I.D. & A.
MELBOURNE OFFICE
71 QUEENS ROAD
MELBOURNE DATUM RL290 CENTRELINE DATUM RL299 CENTRELINE CHAINAGE DATUM RL305 CENTRELINE CHAINAGE CHAINAGE 6400.000 6409.645 8000.000 318.295 4800.000 303.371-4806.638 303.428-8018.097 318.918 8019.916 317.603 DEEP HOLE
LOWER WIMMERA RIVER
ROAD CROSSING 826.284 303.422 8046.145 318.594 857.329 303.632 6475.061 312.508 303.548 8094.263 320.266 6500.000 312.719 8119.565 319.203 4921.828 303.747 536.506 313.027 8144.236 TOM THE TAYLOR CREEK 303.645 8163.128 319.246 IL WALL RL 303.93m TOP DROP STRUCTURE RL 307.03m 596.875 319.726 622.527 312.629 8245.250 320.043 8258.306 321.800-START OF HANGING SWAMP 6672.219 313.118 6689.849 6700.220 313.431 313.818 5118.128 306.989 727.014 314.27 5140.635 307.038 760.690 314.443 167.435 307.225 185.075 307.227 797.974 314.627 5205.196 307.524 5249.186 307.399 6849.589 314.966 885.728 315.09 5296.846 307.158 6918.137 315.456 \$354.246 307.244 980.289 315.58 385.548 307.205 7000.000 315.435 7010.674 315.353 5431.385 307.520 \$448.834 307.507-\$500.000 | 307.191 5501.965 | 307.179 7101.770 314.860 528.637 307.373 7133.810 314.06 5554.915 307.282 7180.159 315.147 606.568 307.292 7227.046 316.179 647.990 307.486 7275.635 315.672 680.082 720.886 307.438 314.90 7330.154 5751.790 307.666 315.91 355.262 DEEP WATER HOLE 316.01 7391.671 5802.481 308.634 7417.325 316.230 \$844.777 308.172 Datum
Hortzontal 1:2500
Vertical 1:250 7461.196 316.034 RIVER INACCESSIBLE 913.477 308.948 5937.491 308.907 5981.018 309.446 000.000 309.427 7611.063 316.700 7611.123 316.707 6037.282 309.390 6064.541 309.096 SURVEY & MAPPING GROUP GEELONG. Ph (03) 52 264200 Fisher Stewart 7680.016 316.429 309.191 A NEWMAN R HUNTER 3123.425 7728.156 317.022 7744.177 317.054 HOR 1: 2500 Ą 1:250 7804.272 317.170 209.686 310.127 10/01/02 0 25 50 6232.036 310.446 7836.313 317.450 6245.656 311.131-6261.055 311.587 LONGITUDINAL SECTIONS CH 4800 - 8258.306m WIMMERA RIVER ELMHURST **Drawing No. 1701577-G2**Sheet No. 2 of 2 7872.549 316.908-7884.420 316.181-7893.408 317.197-Sheet No. 2 of 2
© Earth Tech Engineering Pty Ltd ABN 61 089 482 888 302.294 311.659 7912.592 317.40 **ĕ₩**₫ 355.978 311.939 LITTLE WIMMERA RIVER DEEP WATER HOLE 3 8 6400.000 311.941-8 48 Rev

D

1701577-G2.dwg A1